
Temperature metering PT1000 (°C/°F)

- Standard: 2 setpoints, min/max memory optional analogue output
- Mounting into panels with thickness up to 50 mm





(supply voltage 24 VDC galv. insulated)

Power supply 24 VDC 2-wire (600,0°C) galvanic insulated (11=plus, 10=minus) PTE 4.606.6722B

Options

- green LED
- Protection IP54
- Protection IP65
- Analog output 0-10 VDC (12 bit)
- ullet Analog output 0-20 mA/load 500 Ω (12 bit)
- ullet Analog output 4-20 mA/load 500 Ω (12 bit)
- Analog output 0-10 VDC (12 bit)
- Analog output 0-20 mA/load 500 Ω (12 bit) (supply voltage 24 VDC galv. insulated)
- Analog output 4-20 mA/load 500 Ω (12 bit) (supply voltage 24 VDC galv. insulated)

With analog output setpoint S1 is not available!


- Dimension strips are selectable (max. 7 characters)
- Other power supplies on demand

Technical data

 $72 \times 36 \times 97$ mm, including screw terminal $68.0^{+0.7} \times 33.0^{+0.6}$ mm **Dimensions** Housing Assembly cut out Fastening special quick plastic clamp proper to fix in wall thickness up to 50 mm Housing material PC/ABS blend, colour black, UL94V-0 at the front IP40 Protective system connection IP00 approx. 0.190 kg Weight Connection at the rear side via screw terminals up to 2.5 mm² Input PT1000 Measuring range -99.9 up to +600.0°C 0.1°C Resolution Linearization according to DIN IEC751 Sensor current approx. 0, mA charge 240 VAC/0.25 A - 24 VDC/1 A, with ohm resistive burden 2 * 10^5 at max. contact rating Output Relay output Switching cycles 10 * 10⁶ mechanically Open collector supply by customers (U_B=5-40 V/I_{max}=100 mA) 0-10 VDC (12 bit) Analogue output The analogue output is galvanic insulated from the 0-20 mA (12 bit) - load 500 Ohm measuring input! 4-20 mA (12 bit) - load 500 Ohm **Accuracy** Resolution $R_L \le 10 \Omega = +/-1K$ Messfehler $R_L > 10 \Omega \le 20 \Omega = +/-2K$ 100 ppm/K Temp. drift Measuring principle voltage/frequency converter 230/115 VAC +/- 10% (50-60 Hz), 24 VDC +/-10% galvanic insulated Power unit Supply voltage Power consumption approx. 3 VA Indication Display LED with 7 segments, 14 mm high, red 4-digit = indication 9999 Overflow indication of 4 transversal bars Indication time from 0.2 up to 10.0 seconds adjustable Ambient Working temperature 0 up to + 60°C

Housing:

conditions




CE-sign

Storing temperature

-20 up to + 80°C

For unlimited use of the instrument within the directives for electromagnetic compatibility 89/336/EC measuring wires have to be used with shielded cable and cable's shield connected to earth ground at one end only.

Connection diagram, programming, remarks



Setting

- 1. Connect the instrument according to the wiring diagram.
- 2. After power on, the instrument runs into a lamp test and returns back to the standard mode.
- 3. Pressing the **P**-key enters the program mode with indication of **P2** on the display.
- 4. Pressing the **P**-key and **△**-key simultaneously steps through the different program numbers.
- 5. Pressing ▲ or ▼-key shows the current values.
- To change values use ▲ or ▼-key.
- The remaining values will be memorized automatically 7 seconds after the last touch of key with leaving program mode.

Additional key-functions in standard mode for indication of min/max values.

Simultaneously pressing of ▼ and ▲ key deletes and actualizes min/max-memory.


- ▲ key enters max-memory.
- ▼ key enters min-memory.

Instructions


After power on the instrument with his inbuilt microcontroller starts with an initial program activating lamp test and readout of memorized parameters in an EEPROM.

The following diagrams are showing the switching operation of PVE4 relay contacts. The hysteresis is free programmable. There are two kinds of operation:

Example: operation current



Example: quiescent current



Operation current means that the open collector will be pulled in (conducting) if reaching the adjusted setpoint.

Quiescent current means that the open collector will be dropped out (cutoff) if reaching the adjusted setpoint.

Operation, setting instructions

Subject to technical alteration - status 02/2006 - PTE466GB.DOC

Program table 1

Program- Number (PN)	Function	Remark	Display	Basic parameters after reset
2	Sensor and line balancing	Temperature is displayed	0 to +/-20.0	0.0
3	Selection between °C or °F	Celsius=0 / Fahrenheit=1	0/1	0
4	Input of display time	Display time = measuring time Method of measurement integrating	0.2 to 10.0 seconds	1.0
5	Input of final value for analog output	Option	-999 to +9999	500.0
6	Input of offset for analog output	Option	-999 to +9999	0.0

Program table 2

(setpoints)

S1	S2	Function	Display	Basic parameters after reset
PN	PN			
61	66	Setpoint	-999 to +9999	100.0/150.0
62	67	Hysteresis	0 to +9999	0.1/0.1
63	68	Quiescent current	0	-
		Operating current	1	1/1

Example for programming

Temperature sensor: PT1000 **Connection:** 2-wire

Display: 0.0 up to 600.0 °C **Display refresh time:** 2.0 seconds


Setpoints: S1 ==> 60.0 and guiescent current

open collector conducting = 58.0 ==>hysteresis 2.0

S2 ==> 150.0 and operation current

relay drop out = 80.0 ==>hysteresis 70.0


Analog output: 0 V output ==> display 0.0 ==> 0.0° C (no setpoint S1) 10 V output ==> display 600.0 ==> 600.0° C



The basic adjustments concerning to the following program example are the ground parameters after a total reset occurring through a power on with pressing \mathbf{P} -key (see previous page).

Program advices:


Pressing the **P**-key enters **always** the program mode with program number **2**. The **P2** starts to blink in change with the current value after 3 seconds. After further 4 seconds the system leaves the program mode and goes to the standard mode. In program mode pressing \blacktriangledown or \blacktriangle -key selects the current values which are free scalable with both the keys. All the other parameters will be memorized automatically after leaving program mode.





To program number 2 with P.
To memorized value with ▼ or ▲.
Sensor and line balancing.

To program number 3 with P and ▲. P A
To memorized value with ♥ or ▲.
To program number 4 with P and A. P A

Example for programming







Subject to technical alteration status 02/2006 – PTE466GB.DOC