


Strain gauge amplifier for weighing application

- Standard: 2 setpoints, min/max memory, IP54, plug in terminal

- Mounting into panels up to 50 mm – optional: analog output


96x48

8888



ORDER NUMBER OF TYPE

PWE 4.20x.1592B



Power supply 115 VAC
(connection via terminal 14 and 15)

PWE 4.20x.1492B

Power supply 24 VDC
- **galv. insulated** - (15=plus, 14=minus)

PWE 4.20x.1792B

Options


- Green LED
- Plug in terminal and protection IP65
- Analog output 0-10 VDC (12 bit)
- Analog output 0-20 mA/load 500 Ω (12 bit)
- Analog output 4-20 mA/load 500 Ω (12 bit)
- Analog output 0-10 VDC (12 bit) *(supply voltage 24 VDC galvanically insulated)*
- Analog output 0-20 mA/load 500 Ω (12 bit) *(supply voltage 24 VDC galvanically insulated)*
- Analog output 4-20 mA/load 500 Ω (12 bit) *(supply voltage 24 VDC galvanically insulated)*
- Other power supplies on demand

Technical data

Dimensions	Housing	96 x 48 x 134 including screw terminal
	Assembly cut out	92.0 ^{+0.6} x 45.0 ^{+0.6} mm
	Fastening	special quick plastic clamp proper to fix in wall thickness up to 50 mm
	Housing material	PC/ABS-plastic blend, colour black, UL94V-0
	Protective system	at the front IP54 connection IP00
	Weight	approx. 0.450 kg
	Connection	At the rear side via screw terminal up to 2.5 mm ²
Input	Measuring range	1 mV/V – 2 mV/V – 3.3 mV/V
Output	Sensor supply	10 VDC/350 Ω (power supply for other strain gauges)
	Relay output	charge 230 VAC/5 A – 30 VDC/2 A, with ohm resistive burden
	Switching cycles	0.5 * 10 ⁵ at max. contact rating 5 * 10 ⁶ mechanically
	Analogue output	Separation appropriate to DIN EN 50178/ Specification appropriate to DIN EN60255 0-10 VDC (12 bit) 0-20 mA (12 bit) - load 500 Ohm 4-20 mA (12 bit) - load 500 Ohm
Accuracy	Resolution	-999 up to +9999
	Measuring fault	+/-0.2 % of measuring range, +/- 1 digit
	Temp. drift	100 ppm/K
	Measuring principle	voltage/frequency converter
Power unit	Supply voltage	230/115 VAC +/- 10 % (50-60 Hz), 24 VDC +/-10 % galvanic insulated
	Power consumption	approx. 5 VA2
Indication	Display	LED with 7 segments, 14 mm high, red 4-digit = indication 9999
	Overflow	4 bars up
	Underflow	4 bars down
	Measuring time	adjustable from 0.2 up to 10.0 seconds
Ambient conditions	Working temperature	0 up to + 60 °C
	Storing temperature	-20 up to + 80 °C

The analogue output is galvanic insulated from the measuring input!


Housing:



CE-sign

For unlimited use of the instrument within the directives for electromagnetic compatibility 89/336/EC analog input wires have to be used with shielded cable and cable's shield connected to earth ground at one end only.

Wiring diagram, programming, instructions



Adjustment (also see programming example on the next page)

1. Connect the instrument according to the wiring diagram. Connect screening of sensor line with protective conductor.
2. Switch on supply voltage. There is a segment test with switching-over to operating mode.
3. Charge DMS probe or sensor, respectively, with minimum load (in the case of a scale, by putting on a reference weight).
4. Press program key [P]. Program number 1 lit.
5. Change the program number by simultaneously pressing program key [P] and key [▲].
6. Pressing the key [▲] or [▼] results in a change of indication to the value stored under this program number.
7. Change the indicated value by pressing key [▼] or [▲].
8. Effect storing by pressing keys [P] & [▼].
9. Charge DMS probe or sensor, respectively, with maximum load (in the case of a scale, by putting-on a reference weight).
10. Press program keys [P] & [▲] until program number 2 lights up and continue in correspondance with item 6.
11. Without pressing of any key, the device changes to the operating mode after 7 seconds. With this, final storing of all adjusted values is effected.

Calling of MIN/MAX values from memory

Press key [▲] to indicate **MAX** memory. Press key [▼] to indicate **MIN** memory.
Simultaneous pressing of keys [▼] and [▲] deletes and updates the **MIN/MAX** memory.

Counterbalancing

Operator

Device

Press key [0] (TARA)

Indication of counterbalancing with continuous zeros. The "offset" value stored under PN2 is indicated.

Note

Overflow/underflow

In the case of a display overflow, the display shows 4 horizontal bars in the upper indication section. In the case of a display underflow, the display shows 4 horizontal bars in the lower indication section. If PN8 = 1...3 has been selected, then the starting value, defined under PN1 as -12.5% of the measuring range, is evaluated as the underflow value and the end value, defined under PN2 as +12.5% of the measuring range, is evaluated as the overflow value. With the configuration PN8 = 4...6, only the sensor sensitivity is tested and used for the evaluation of an overflow or underflow. The calibration points defined under PN1 and PN2 are used for the linearization.

Error messages

After switching-on of the supply voltage, the device starts a self-test including a segment test (all LEDs lit). Should any disturbance occur during this procedure, this is indicated by „HELP“ on the display. That is also valid with running operation. The function serves to grant security to all surrounding components and installations. After a „HELP“ indication, a basic reset has to be performed by pressing key **P** and, simultaneously, connecting the supply voltage. As long as key **P** is pressed, the display performs a segment test and then the parameter entered ex works are taken over. After this, the device has to be programmed to have the parameters required by the user.

Analog output


The parameters of the analog output refer to the values set under PN1 and PN2. After counterbalancing, the analog output does not shift its zero point. With this output, the measuring value actually present on the input is represented.

Switching points

The following diagram illustrates the switching behaviour of the relay outputs for devices having switching points. The parameters for each switching point are freely programmable. In the operating current mode, the respecting relay actuates with reaching the switching threshold, in the quiescent current mode, the respecting relay falls off when the switching threshold has been reached. This way, a failure of the supply voltage can be indicated by an alarm.


Definition: Hysteresis is the width of the “window” between two threshold values.

Example: operation current



Operation current means that the relay will be pulled in if reaching the adjusted setpoint.

Example: quiescent current



Quiescent current means that the relay will be dropped out by reaching the adjusted setpoint.

Operation, setting instructions

Subject to technical alteration - status 04/2006 - PWE431GB


Program table

Program-number (PN)	Function	Remark	Display	Factory settings
1	Indication of desired initial value	stored with [P] & [▼]	-999 up to +9999	0.0
2	Indication of desired final value	stored with [P] & [▼]	-999 up to +9999	200.0
3	Setting of decimal point	with ▲ to the desired decimal point		000.0
4	Display refresh	refresh of the display value	0.2 up to 10.0 seconds	1.0
5	Final value for analog output	option	-999 up to +9999	200.0
6	Offset for analog output	option	-999 up to +9999	0
7	Tara key and counterbalancing	no key front key external key both keys no key front key external key both keys	no counterbalancing no counterbalancing no counterbalancing no counterbalancing auto-counterbalancing auto-counterbalancing auto-counterbalancing auto-counterbalancing	0 1 2 3 4 5 6 7
8	Input of the measuring range Range monitoring on PN1/PN2 Sensor sensitivity monitoring	1 = 1 mV/V – 2 = 2 mV/V – 3 = 3.3 mV/V – 4 = 1 mV/V – 5 = 2mV/V – 6 = 3.3 mV/V stored with [P] & [▼]	1 / 2 / 3	2
61	Setpoint 1		-999 up to +9999	100.0
62	Setpoint 1 hysteresis		0 up to +9999	1
63	Setpoint 1 operating/quiescent current	0 = R / 1 = A	0 / 1	0
64	Setpoint 1 delay time		0.0 – 10 seconds	0.0
66	Setpoint 2		-999 up to +9999	1500
67	Setpoint 2 hysteresis		0 up to +9999	1
68	Setpoint 2 operating/quiescent current	0 = R / 1 = A	0 / 1	0
69	Setpoint 2 delay time		0.0 – 10 seconds	0.0

Before the first operation or after a change of the above mentioned parameters, a calibration is necessary!

Example for programming

Measuring range: 2 mV/V
Measuring signal: 0 – 20 mV
Display: 0 – 300.0
Display refresh: 2.0 seconds
Setpoints: S1 ==> 60.0 and quiescent current
 relay pull in= 58.0 → hysteresis 2.0
 S2 ==> 150.0 and operation current
 relay drop out = 80.0 → hysteresis 70.0
Analogue output: 0 V Output ==> Display 0.0 ==> Measuring signal 0 mV
 10 V Output ==> Display 300.0 ==> Measuring signal 20 mV



The basic adjustments concerning to the following program example are the factory settings.

Program advices

Pressing the P-key enters **always** the program mode with program number 1. The "P1" begins to blink in change with the current value after 3 seconds. After further 4 seconds the system leaves the program mode and goes to the normal mode. In program mode pressing ▼ or ▲-key selects the current values which is free scalable with both of the keys. Under program number 1 and 2 the memorization will be executed by pressing the P- and ▼-key simultaneously - 4 horizontal bars indicates the storage. All other parameters will be stored automatically after leaving program mode.

Programming.

Switch power on!

Segment test

8.8.8.8.

normal mode

0.0

Enter program mode

P 1

To the stored value with ▼ or ▲

0.0

Store at scale without load by pressing P and ▼. Take over by display of transversal bars.

- - - -

To program number 2 with P and ▲

P 2

To the stored value with ▼ or ▲

200.0

Set free scalable value


300.0

To program number 3 with P and ▲


P 3

Example for programming


Burden scale with the desired reference emphasis and press P and ▼.




To program number 3 mit P und ▲.



To the stored value with ▼ or ▲.



To program number 4 with P and ▲.



To the stored value with ▼ or ▲.




Set display time.



The following programming steps are necessary for the setpoint programming of S1 and S2 only.

To program number 61 with P and ▲




To the stored value with ▼ or ▲



Set free scalable value for setpoint S1



To program number 62 with P and ▲




To the stored value with ▼ or ▲




Set hysteresis for S1




To program number 63 with P and ▲



To the stored value with ▼ or ▲



To program number 66 with P and ▲




To the stored value with ▼ or ▲




Set free scalable value for setpoint S2



To program number 67 with P and ▲



To the stored value with ▼ or ▲




Set hysteresis for S2




To program number 68 with P and ▲



To the stored value with ▼ or ▲




Set operation current



The program numbers 5 and 6 are available with option analogue output only.

To program number 5 with P and ▲




To the stored value with ▼ or ▲



Set free scalable final indication value for analogue output.



To program number 6 with P and ▲



To the stored value with ▼ or ▲



Programming finished.

All programmed values are memorized after 7 seconds. Jumps back into standard mode automatically. Calibration necessary!

Setting possibilities of the jumper field on the rear side.

