# Bargraph Indicator direct voltage, direct current

- Standard: bar or dot indication
- Allows to be placed side by side in grid and mosaics systems
- Mounting into panels with thickness up to 50 mm




ORDER NUMBER OF TYPE

**BVO 1.001.776B** 

BHO 1.001.776B

# BVO1.001.776B ORDE


#### BVO2.001.576B




Power supplyy 24 VDC (72x24 vertically) B' Power supply 24 VDC (72x24 horizontally) B'

BVO 2.001.576B BHO 2.001.576B

BHO2.001.576B




# Connection



# **Technical data**

Dimensions	Housing Assembly cut out Housing Assembly cut out Fastening Housing material Protective system	72 x 24 x 106 mm, including screw terminal $68^{+0.7}$ x 22.2 <sup>+0.3</sup> mm 48 x 24 x 100 mm, including screw terminal 45.0 <sup>+0.6</sup> x 22.2 <sup>+0.3</sup> mm special quick plastic clamp proper to fix in wall thickness up to 50 mm PC/ABS-plastics blend, colour black, UL94V-0 at the front IP40 connection IP00
(72x24) (48x24)	Weight	approx. 80 g approx. 60 g at the rear side via plug in terminal up to 1.5 mm <sup>2</sup>
Input	Measuring range	050  V (U <sub>min</sub> =5 V, U <sub>max</sub> =60 V); 0/420 mA (I <sub>min</sub> =8 mA, I <sub>max</sub> =25 mA) all ranges are selectable via connection terminal / offset adjustment supported by offset potentiometer Ri with 50 V = 100 K <sub>Ω</sub> 20 mA = 100 Ω
Accuracy (72x24) (48x24)	Resolution Resolution Measuring fault Temperature drift	20 digit 10 digit +/- 1 digit 100 ppm/K
Power unit	Supply voltage Power consumption	24 VDC +/-10 % galvanic insulated approx. 1.5 VA
Indication (72x24) (48x24) Ambient conditions	Display Display Working temperature Storing temperature	bar indication 20 digit red / optionally green bar indication 10 digit red / optionally green 0 up to + 60 $^{\circ}$ C -20 up to + 80 $^{\circ}$ C
Housing:	Storing temperature	



<u>CE-sign</u> For unlimited use of the instrument within the directives for electromagnetic compatibility 89/336/EC analogue input wires have to be used with shielded cable and cable's shield connected to earth ground at one end only.

# Handling, connection diagrams

#### **Description:**

- 1. Connect the instrument according to the wiring diagram and turn power on.
- 2. Setting of display value in the case of IP40 and IP54: Detach the front pane with a small screwdriver leading between front panel and housing frame.

48x24

Offset

۲

ij


Fullscale

0


ij

- 3. Set the desired offset value (input voltage/current) und adjust the desired indication value by means of the offset potentiometer.
- 4. Set the desired full scale value (input voltage/current) und adjust the desired indication value by means of the full scale potentiometer.
- 5. In order to achieve a full display a least tension of 5 V and/or least current of 8 mA is required at the measuring inputs.
- 6. Insert front pane cautiously again. (it only applies to IP40 and IP54)

## Setting options front side (IP40 and IP54)




# Setting options rear side (IP65)





## **Connection diagrams**

2-wire: 4-20 mA

3-wire: 0-20 mA 4-20 mA







0-10 V/0-5 V

1-6 V

3-wire: